


T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 30 Corner common to sections 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	_____
Diameter	<u>5"</u>	<u>4"</u>	_____
Bearing	<u>N56W</u>	<u>S52 1/2 E</u>	_____
Distance	<u>20 LKS</u>	<u>17 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURCO
Location filed COUNTY SURVEY RECORD BOOK B P 178-211
Monument FIND OLD GOVT B.T STUMP: 4" BL. PINE
S52-30E 17 LKS.
1916, A.W. NOWAK BOOK B P 606 FIND CORNER

Evidence of Subsequent Corner Restoration

Year of search 1975 By Walter Curco
Found railroad spike 8" deep 1' East of center.
Set cast iron monument 4" dia. x 20" long
under surface of Co. Rd # 118.

Doc. # 223896 CERT. OF LOCATION

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>J. PINE</u>	_____
Diameter	<u>12"</u>	<u>5"</u>	_____
Bearing	<u>N64-33E</u>	<u>S34-25E</u>	_____
Distance	<u>50.62'</u>	<u>17.08'</u>	_____

1912 B.T.S

Bearing Trees, Reference Objects

<u>Norway Pine</u>	<u>White Oak</u>	<u>Red Oak</u>	<u>Red Oak</u>
<u>8"</u>	<u>5"</u>	<u>5"</u>	<u>8"</u>
<u>N16° 35' W</u>	<u>N32° 03' W</u>	<u>N60° 45' E</u>	<u>S63° 54' W</u>
<u>111.63'</u>	<u>66.80'</u>	<u>60.43'</u>	<u>39.55'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - BALSAM HIGH OVER
M. RON LANDECKER 1976

CERTIFICATE - WALT CURCO - 1975
DOC # 223896

OCT 2003 M. Landecker # 7452
Certs of Surv. shows Mon. found

march 1912, John W. Curco
Trwp rd order shows survey