


T. 137 R. 30 M. 54H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 11 Corner common to sections 12, 14, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	N. PINE	N. PINE	N. PINE	N. PINE
Diameter	<u>12"</u>	<u>12"</u>	<u>12"</u>	<u>12"</u>
Bearing	<u>N34E</u>	<u>N46W</u>	<u>S48W</u>	<u>S66E</u>
Distance	<u>53 LKS</u>	<u>31 LKS</u>	<u>35 LKS</u>	<u>37 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1984 By Walt Curo  
Certificate - Fnd rotted oak post in center of  
rock pile - distances to S 1/4 & E 1/4 fit well  
with orig. - several stumps badly burned in area  
set 2" square X 36" county man w/ alum. cap

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Rock	Rock	Rock	Rock
<u>6"</u>	<u>8"</u>	<u>8"</u>	<u>10"</u>
<u>N46E</u>	<u>S18W</u>	<u>S62W</u>	<u>N45W</u>
<u>41.70'</u>	<u>34.12'</u>	<u>20.63'</u>	<u>29.82'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Walt Curo 1984 Doc # 278540