


T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
N114 24 E Corner common to sections 13, 24
MC#6



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species N. Pine N. Pine
Diameter 10" 12"
Bearing N34E S43E
Distance 39 LKS 160 LKS.

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1911 By HARRY S. TODD
Location filed COUNTY SURVEY RECORD BOOK "A" P 373-377
Monument FIND CORNER SET PREVIOUSLY BY CURE
SET 2X 48" GALV. I.P. IN CONCRETE
1915, F.A. DONNER, BOOK "C" P 39 FIND I.M. SET BY CURE
also on microfilm - roll 115 OK 19 P. 37, 57, 123

Evidence of Subsequent Corner Restoration

Year of search 1942 By JOHN CURE
COUNTY BOOK "D" P 298-299 FIND 2 1/4 X 48" I.M.
1954, HAROLD CURE, BOOK "D" P 420 FIND I.M. AND
1942 TIES - NOW NORTH I. 547W

Bearing Trees, Reference Objects

Species A SH W. PINE
Diameter 5" 2"
Bearing N52-33W N7-05E
Distance 44.40' 61.15'
1911 ties

Bearing Trees, Reference Objects

W. PINE J. PINE
12" 14"
N6E S53W
60.40' 46.50'
1942 TIES

N-23

Subsequent Corner Restoration

Year surveyed 1967 By RF Scheider
Location filed Survey for DMK - Map in File
Monument Found iron marker in place

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

7/01 CCSO found 2 3/4" OD plumbers
Cap, flush, 8'± W. of Drive and 28'±
S. of boat ramp. Witness as follows:

20" W. Pine N6°E, 60.52'
14" N. Pine S60°E, 37.06'*
5" N. Pine S4°W, 23.06'*
*distance to double head nail

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____