


T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 21 Corner common to sections 21, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Bl. Pine
Diameter 8"
Bearing N53E
Distance 168 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed: 1959 By Dept of Nat. Resources
Location filed Map in File
Monument Find 3/4" iron pipe at P. 1 N-S
Twp Road & E-W fence

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - WALT Curu - 1975
Doc. # 223882
Found 3/4" x 5' pipe bent over 2' under fill.
Set cast iron monument 4" dia. top x 20"
long under surface of Twp. road. TIES:
8" Birch N 70° 43' E 119.46'; 6" Jack Pine
S 31° 14' E 138.61'; Power pole S 04° 31' E
103.28'

1999 - Freeman #21367 - Certificate
indicates monument found.

2004 May T. Freeman #21367
Cert. of Sur. Shows mon. found

Aug. 2004 J. Kramer #23668
Cert. of Sur. Shows mon. found