


T. 139 R. 30 N. 5TH Coordinates: X _____ Y _____
E 14 23 Corner common to sections 23, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Bearing Trees	
Species <u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>20"</u>	<u>24"</u>
Bearing <u>S79E</u>	<u>N68W</u>
Distance <u>56 LKS</u>	<u>29 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1911 By HARRY S. TOOD

Location filed COUNTY SURVEY RECORD BOOK "A" P 313-317

Monument END STUMPS OF BOTH OLD GOVT. BITS.
SET 2x4x8" GALV. IIP. IN CONCRETE
1915, F.A. DENNER, BOOK "D" P 39 END LIM. SET BY CURD
- also on microfilm - roll 115 BK 79 P. 37

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Evidence of Subsequent Corner Restoration

Year of search 1954 By HAROLD CURD

COUNTY BOOK "D" P. 420 END CORNER

Bearing Trees, Reference Objects

<u>J. Pine</u>	<u>J. Pine</u>
<u>8"</u>	<u>10"</u>
<u>N13-36E</u>	<u>N34-40W</u>
<u>35.85'</u>	<u>47.95'</u>

P-21 Subsequent Corner Restoration

Year surveyed 7/01 By CCSO

Location filed file # 2001, 035

Monument Found 1 1/2" ODIP, down 0.1'
on E Hwy #87, on fence line south,
12'± W. of Driveway. Witness as follows:

<u>10" W. Pine</u>	<u>N35°E, 85.50'x</u>
<u>10" W. Pine</u>	<u>S38°W, 48.09'x</u>
<u>6" R. Oak</u>	<u>N10°W, 39.63'x</u>

*distance to double head nail

Dec 2002 O. Pearson # 11752
Svy. report shows Mon. found

Apr 2003 B. Grivna # 17253
Cert. of Svy. shows Mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - ECHO HILL
HAROLD CURD 1955