


T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 28 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	
Diameter	<u>10"</u>	<u>6"</u>	
Bearing	<u>S6W</u>	<u>N14W</u>	
Distance	<u>18 LKS</u>	<u>13 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1927 By Co Hwy DEPT.

Location filed _____

Monument CONCRETE MON.

Co DITCH SURVEY BK 3 BOX 1 OF Co

DITCH SURVEY BOOKS PG 3

Evidence of Subsequent Corner Restoration

Year of search 7/01 By CCSO

Found PK nail, 0.15' N. of E Hwy, #87,

on mowed line. Conc. Pillar only

remaining 1975 witness, add following:

Bearing Trees, Reference Objects

Species	<u>Conc. Mon</u>	<u>Conc. Mon</u>
Diameter	<u>4"</u>	<u>4"</u>
Bearing	<u>N52-30W</u>	<u>S37-30W</u>
Distance	<u>46.67</u>	<u>46.47</u>

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Spruce</u>	<u>P. Pole</u>
<u>5"</u>	<u>12"</u>	
<u>N45°W</u>	<u>N6°E</u>	<u>S28°E</u>
<u>72.84'*</u>	<u>36.61'*</u>	<u>43.39'*</u>

*distance to double head nail

R 11

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - A.R. TAUBMAN ASST Hwy ENGINEER

1927

CERTIFICATE - WALT CURA - 1975

Doc. # 223887

Found PK nail. Set cast iron monument

4" dia. top x 20" long flush with surface

C.S.A.H. # 87. Ties: SW corner concrete

pillar N14°00'E 33.73'; 14" Jack Pine N47°

57'E 57.74'; Power Pole S30°37'E 43.13'.

1999 - Freeman # 21367 - Certificate

indicates monument found

May 2004 T. Freeman # 21367

cert. of Sur. Shows mon. found

Dec 2004 B. Grivna # 17353

Cert. of Survey shows monument found