


T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Trces	Distance
<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>N. PINE</u>
<u>8"</u>	<u>7"</u>	<u>8"</u>	<u>15"</u>
<u>N84E</u>	<u>N35W</u>	<u>S84E</u>	<u>S3W</u>
<u>425 LKS</u>	<u>170 LKS</u>	<u>410 LKS</u>	<u>324 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURA
Location filed COUNTY SURVEY RECORD BOOK "A" P 150-151
Monument FWD OLD GOVT. B.T.S: 8" BL. PINE N84E 280.5'
8" BL. PINE S84E 275.9', 15" N. PINE S3W 213.8'
SET 8X8X36" CEMENT POST

Evidence of Subsequent Corner Restoration

Year of search 1967 By R. F. SCHNEIDER
Set Cass County cast iron monument.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POWER POLE</u>	<u>TEL. POLE</u>	<u>TEL. POLE</u>	
<u>SW</u>	<u>NE</u>	<u>NW</u>	
<u>48.40'</u>	<u>43.25'</u>	<u>91.90'</u>	

R - 9

Subsequent Corner Restoration

Year surveyed Aug, 1959 By CCSO
Location filed CCSO
Monument Found CIM, down 0.7' on
& Hwy. #87, 4'E. & CR #117 South.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - R.F. SCHNEIDER - 1967

PK W. end CMP N9°W, 61.33'
8" P. Oak N25°E, 99.81' *
8" W. Oak S20°E, 81.11 *
P. Pole S44°W, 49.05 *
* distance to double head nail