


T. 139 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 17 Corner common to sections 8, 9, 16, 17
MC# 10



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	
Diameter	<u>8"</u>	<u>6"</u>	
Bearing	<u>N7W</u>	<u>N13 1/2 E</u>	
Distance	<u>150 LKS.</u>	<u>211 LKS.</u>	

Original Evidence Found

Year of search 1905 By Hallett
Monument found GLO BT'S

Original Bearing Trees Found

Species	<u>Black Pine</u>	<u>Black Pine</u>
Diameter	<u>8</u>	<u>6</u>
Bearing	<u>N7W</u>	<u>N13 1/2 E</u>
Distance	<u>158</u>	<u>211</u>

Subsequent Corner Restoration

Year surveyed DEC. 1970 By R.F. SCHNEIDER
Location filed _____
Monument PLAT OF REUCKS GOOSE LAKE SHORES
INDICATES IRON PIPE IN PLACE

Evidence of Subsequent Corner Restoration

Year of search 6/03 By CCSO
Found 3/4" OD IP, capped RLS #17253,
Flush, 12'± from Lake.

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>J. Pine</u>	<u>R. Oak</u>	<u>7/8" IP</u>
<u>12"</u>	<u>15"</u>	<u>14"</u>	<u>RLS 17253</u>
<u>N12°E</u>	<u>S70°W</u>	<u>N50°W</u>	<u>North</u>
<u>10.19'*</u>	<u>19.18'*</u>	<u>6.91'*</u>	<u>33.00'</u>

*denotes double head nail

J-9

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - REUCKS GOOSE LAKE SHORES
R.F. SCHNEIDER 1970
Sept. 1905 W.H. Hallett
Trwpd order shows survey

