


T. 140 R. 25 M. 5th Coordinates: X _____ Y _____
E 1/4 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>Yellow Pine</u>	_____
Diameter	<u>6"</u>	<u>3"</u>	_____
Bearing	<u>N 9° E</u>	<u>S 20° W</u>	_____
Distance	<u>29 links</u>	<u>10 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 11/1910 By M. Watson, Surveyor
Location filed: Smoky Hollow Township Road Order, #9
Monument:
Surveyors Report shows a road on the E. - W. 1/4 line of sections 7 - 10, beginning at the 1/4 corner of sections 10 and 11.

Evidence of Subsequent Corner Restoration

Year of search 12/1916 By A. Nowak, Assistant Engineer
Location filed: Survey Record 305, Book B, pg 329-330, and Curo
Monument: Set hub on PI of centerline E. and N.t Curo Book 55, pages 35, 39, 40 and 66, survey of Co. Rd., states walk to 1/4 Cor. Secs 9 & 10, on W. end graded rd. which runs through center of Sec. 10, road turns on 1/4 Cor. to N. on Sec. line. GLO bearing trees have disappeared.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	_____	_____
Diameter	<u>7"</u>	_____	_____
Bearing	<u>South</u>	_____	_____
Distance	<u>7.70'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed Circ 1916 By A. Nowak, Assistant Engineer
Location filed: Road Calendar Book B, page 47
Monument:
Indicates a proposed road and is very similar to a drawing on page 66 of A. Nowak's notes.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

1937, CCC personnel
Washburn Lake notes, Book 1, page 42
states Set app. 1 mile post 77.96 CH E. of W 1/4.


9/2005, CCHD/SO
#2004.011
Searched area, located the intersection of Co. Rd. #161 and Hawk Homestead Trail to the N., no evidence of corner found.

10/2019, CCHD/SO
#2018.007
Set 0.5" rebar, capped RLS 21367, down, 0.5' at intersection of centerlines Co. Rd. #161 and Hawk Homestead Rd. and witnessed as follows:
7" Burr Oak, N 41° W, 32.04' duplex nail, up 1.0', E. side
16" Red Oak, S 35° E, 41.84' duplex nail, up 1.0', E. side
12" Red Oak, S 54° W, 47.27' duplex nail, up 1.0', N. side

Index No. G 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey
Year surveyed 1867
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species ASPEN Y. PINE
Diameter 6" 3"
Bearing N 9 E S 20 W
Distance 29 LKS 10 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration
Year surveyed 1916 By ALOIS NAWAK
Location filed COUNTY SURVEY RECORD BOOK B P 320-333
Monument SET HUB @ P. I. RD. E & N
also on microfilm - roll 105 BK 55 P. 39-40

Evidence of Subsequent Corner Restoration
Year of search 1937 By CCC
Washburn Lake - BK # 1 P. 42
Set App. 1 mile post 77.96 CH E. of W 1/4

Bearing Trees, Reference Objects
Species N. Pine
Diameter 7"
Bearing SOUTH
Distance 7.70'

Bearing Trees, Reference Objects

G-13

Subsequent Corner Restoration
Year surveyed 1910 By M. Watson
Location filed Twp. Road orders
Monument Surveyors Report indicates road on E-W. 1/4 line.

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____