


Index No. L 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 17 Corner common to sections 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. PINE LYNN  
Diameter 24" 8"  
Bearing S 57 E N 74 W  
Distance 31 LKS 10 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

O = Corner

Subsequent Corner Restoration

Year surveyed Dec. 1998 By C.C. Land Dept. 4/8  
Location filed \_\_\_\_\_  
Monument EXC condition

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1980 By G.H. Stevenson  
Location filed \_\_\_\_\_  
Monument Fd. 2" iron pipe with oval cap and stump of original pine BT.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Trees: 10" Balsam N50E 14.98 }  
10" Maple S65W 15.63 } N±D  
16" Birch S60E 27.20 }  
16" R. Oak S10E 47.40 }  
Pine Stump SE 20.4'

1-27-2000 LEN LANG - ANR-OUTING  
FOUND CORNER IN GOOD CONDITION

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_