


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____


Monument: _____

Monument: _____

Index No. R 11

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 28 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>OAK</u>	<u>OAK</u>	
<u>12"</u>	<u>8"</u>	
<u>S 49 E</u>	<u>N 64 W</u>	
<u>28 LKS</u>	<u>75 LKS</u>	

Species	Bearing	Trees
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed Mar 1999 By Cass Land Dept Adj.
Location filed _____
Monument Found 3/4" pipe RLS 9672
FOUND TIES BY ALS 1996 DATED 8/1990
AS FOLLOWS

Evidence of Subsequent Corner Restoration

Year of search 1987 By W. Buckler
Set 3/4" iron pipe at lost position.

Species	Bearing	Reference Objects
<u>Maple</u>	<u>R. Oak</u>	
<u>8"</u>	<u>12"</u>	
<u>N 86 E</u>	<u>North</u>	
<u>19</u>	<u>11'</u>	

Species	Bearing	Reference Objects
<u>R. Oak</u>	<u>R. Oak</u>	
<u>16"</u>	<u>16"</u>	
<u>N 28 W</u>	<u>S 86 E</u>	
<u>10.65'</u>	<u>12.63'</u>	

R-11

Subsequent Corner Restoration

Year surveyed 9/03 By Landecker & Assoc
Location filed _____
Monument Found 3/4" iron pipe capped
RLS 9672, 30'± N. of pond and
1987 & 1990 witnesses.
A C of L was filed.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared *474530
Filed at CCRO

By *21367
Date 10/7/03