


T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 1 Corner common to sections LAND 6-140-26



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>TAM</u>	<u>TAM</u>
Diameter <u>5"</u>	<u>6"</u>
Bearing <u>S 25 E</u>	<u>S 7 1/2 W</u>
Distance <u>87 LKS</u>	<u>56 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1909 By JOHN CURRO
Location filed COUNTY SURVEY RECORD BOOK A P 308-312
Monument FIND ORIG POST & STUMPS OF 2 BITS: 5" TAM
S 25 E 57.4', 6" TAM S 27 1/2 W 37.0'
1911 - Harry Todd - micro film - roll 115 BK 93 P 24
Find corner previously established by Curro

Bearing Trees, Reference Objects	
Species <u>J. PINE</u>	<u>N. PINE</u>
Diameter <u>6"</u>	<u>2"</u>
Bearing <u>N 11 W</u>	<u>N 63-06 E</u>
Distance <u>177.70'</u>	<u>160.50'</u>
<u>1909 ties</u>	

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK # 6 P. 40
at 5320' from cor. in lake to east - find 1/2 in
middle of road
1938 BK # 20 P. 14 - find 2" 1/2 in cement
for closing corner flush in road.

Bearing Trees, Reference Objects	
_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search SEPT. 2000 By CCSO
Find. in place; 2 1/2" ODIP, down 0.4'. located
3.5' W of E Driveway N/S.

REF. TIES:

<u>8" Spruce</u>	<u>N 2° E</u>	<u>122.91'</u>
<u>11" N. Pine</u>	<u>N 39° E</u>	<u>108.30'</u>
<u>P. Pole</u>	<u>S 11° E</u>	<u>57.47'</u>
<u>4" Aspen</u>	<u>S 75° W</u>	<u>6.28'</u>

Corner GPS CCSO 8/8/02
CCSO fd. 3" ODIP, down 0.3', 3' ± W.
of G