


T. 140 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 14 Corner common to sections 13, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species BALSAM CEDAR  
Diameter 6" 4"  
Bearing S10E N1-45W  
Distance 40 LKS 35 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1909 By JOHN CURD  
Location filed COUNTY SURVEY RECORD BOOK "A" P308-312  
Monument SET 4x4x8" CEDAR POST FROM ROOT OF ORIG BIT:  
4" CEDAR N1-45W 23.1'  
(IN 1911 SET 2 1/2" x 48" I.P. IN CONCRETE)

Evidence of Subsequent Corner Restoration

Year of search 1910 By MAULSTY-CURD  
MICROT. IM - 201115 BK 91 P. 7

Bearing Trees, Reference Objects

Species BALSAM BALSAM  
Diameter 4" 4"  
Bearing S16E S6-BW  
Distance 75' 43.10'

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

L-21

Subsequent Corner Restoration

Year surveyed 6/2001 By CCSO  
Location filed FILE # 2001.027  
Monument Found 2 1/2" OD IP, up 2.5', at  
old fence corner, plumbers cap is  
broken. witness as follows:

- 6" Ash N70°E 35.36' \*
  - 8" Balsam S34°E 23.08' \*
  - 8" Balsam S25°W 35.60' \*
- \*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_