


T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

Species	Bearing	Trees
<u>TAM.</u>	<u>520-50E</u>	<u>5 SPRUCE</u>
<u>4"</u>	<u>155 LKS.</u>	<u>5" SPRUCE</u>
<u>520-50E</u>	<u>155 LKS.</u>	<u>4" SPRUCE</u>
<u>520-50E</u>	<u>155 LKS.</u>	<u>4" SPRUCE</u>
<u>520-50E</u>	<u>155 LKS.</u>	<u>4" SPRUCE</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1938 By CCC
 Location filed Washburn Lake - BK# 9 p. 11
 Monument at 5247' from east of bet N. 49' to 2" See Spruce stake

Evidence of Subsequent Corner Restoration
 Year of search 1991 By David Landecker
 Found 2" square wood post up 12".
Set two 5' rods with 3' stabilizer and aluminum cap in place of wood post.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>8' steel</u>	<u>3' steel</u>	<u>sign post</u>	<u>sign post</u>
<u>8' steel</u>	<u>3' steel</u>	<u>N 45 W</u>	<u>5 45 W</u>
<u>8' steel</u>	<u>3' steel</u>	<u>13.60'</u>	<u>12.30'</u>
_____	_____	_____	_____

V-13

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
1991 Cert. Filed by David Landecker
Doc. # 329225