


T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
E11411 Corner common to sections 11,12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Rock Maple Rock Maple
Diameter 7" 8"
Bearing N57E S60W
Distance 17 LKS 42 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By BEN CLARK
Location filed County Book D P.191
Monument SET OAK POST 3x42"

Evidence of Subsequent Corner Restoration

Year of search 1965 By R. F. SCHMEIDER
COUNTY BOOK "D" P.440 FND I.P. NEW TIES.

Bearing Trees, Reference Objects

Species Redwood MAPLE
Diameter 5" 9"
Bearing S33E S40W
Distance 30' 33'

Bearing Trees, Reference Objects

MAPLE MAPLE MAPLE
12" 10" 16"
S77W S22E S85E
34.3' 27.5' 39.35'

1965 TIES

G-21

Subsequent Corner Restoration

Year surveyed 1983 By Gary Stevenson
Location filed Corner Certificate - Doc # 295284
Monument Fnd I.P. - also 15" maple S40°W 31.5'
that appears to be Ben Clark's A.T.
replaced with cast iron monument
8" Burr oak N49°W 27.28'
16" Maple S73°W 34.89'
13" Red oak N48°E 62.06'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Doc. # 295284
Certificate - Gary Stevenson - 1987
1999 - Landecker & Assoc.
Cert. of Survey indicates iron mon. fnd.

MARCH 2000, CERT. OF LOCATION, MINOR, J. WALKER
DOC. # 430977

FOUND BROKEN CAST IRON MONUMENT, SET
AND SURVEY MONUMENT IN WEST ROAD DITCH

FOUND DBL BLAZE OAK N49°W 27.28'
FOUND DBL BLAZED MAPLE S73°W 34.89'
AND RP DBL BLAZED 10" ASH S70°E 81.92'

April 2004 T. Freeman # 21367
Cert. of Sur. shows mon. found

March 2005 J. Leas # 42619
Cert. of Survey shows monument found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____