


T. 140 R. R8 M. 5TH Coordinates: X _____ Y _____
MC # 16 Corner common to sections 22, 23, 26, 27
NE 27



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species DRY OAK DRY OAK
Diameter 5" 8"
Bearing N70E S60W
Distance 28 LKS 9 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1917 By Ben Clark
Location filed COUNTY BOOK C P. 68
Monument FND GOVT B.T.S: 8" OAK S 60W 9 LKS, OAK STAMP
5" N70E 28 LKS, SET 4' LONG I.P.
1920 - Ben Clark, Book C P. 560 FND I.P.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCG
Washburn Lake - BK# 12 P. 16
at 5240' from South - Fnd I.P. 140' East
of line Fnd BT N 27E 30' from I.P.
1941 - BK# 15 P. 28 at 5280' from South Fnd I.P.
55' SE and another I.P. 16' W.

Bearing Trees, Reference Objects

Species W. BIRCH W. BIRCH
Diameter 8"
Bearing N48W N25-30E
Distance 12' 30'

Bearing Trees, Reference Objects

R-17

Subsequent Corner Restoration

Year surveyed 1959 By DNR - Engineering
Location filed Map & notes in file
Monument Found I.P.
1965 - Co. Hwy Dept. - Co Rd # 54
Found 2" I.P.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Cert. Filed by John Walker / DNR
Doc # 311201
Found 2 1/4" iron pipe, up 2.2'. TIES:
10" Maple 350° 20.20'; 10" Birch 36°
29.02'; 3" Ash 65° 16.80'; 10" Birch 260°
22.93'.

March 1989 J. Walker # 16098
Certificate of Survey shows monument
Found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____