


T. 140 R. R9 M. 5TH Coordinates: X _____ Y _____
M.C.# 26 Corner common to sections 1 AND 6-140-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument POST

Species	Bearing	Trees
<u>Elm</u>	<u>Elm</u>	
Diameter <u>15"</u>	<u>6"</u>	
Bearing <u>N 15 E</u>	<u>N 1 W</u>	
Distance <u>33 lks</u>	<u>28 lks</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1988 By Gary Stevenson

Corner Certificate - Doc # 302549

Find 1/2" I.P. - set 2x2x36" mon. w/ alum. cap

Steel sign post S. 2.10'

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Birch</u>	<u>Birch</u>	<u>Hsh</u>
<u>8" Twin</u>	<u>3"</u>	<u>6"</u>
<u>S 80 W</u>	<u>N 35 W</u>	<u>N 85 E</u>
<u>55.25'</u>	<u>13.35'</u>	<u>24.59'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

DNR SURVEY FIND 2" I.P. TIES INTO TOWNSHIP PLAT FILE

Certificate - Gary Stevenson - 1988