


T. 140 R. 29 M. 5th Coordinates: X _____ Y _____
E 1/4 10 Corner common to sections 10, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Tree
<u>Dead Pine</u>	<u>Dead Pine</u>	
Diameter <u>12"</u>	<u>16"</u>	
Bearing <u>N68E</u>	<u>NS0W</u>	
Distance <u>43 lks</u>	<u>15 lks.</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO
Location filed COUNTY RESURVEY "E-24"
Monument 2 1/4 x 48" I.M.
1915, F.A. DANNER - COUNTY BOOK "C" PR 36 - SET N. PINE
POST
also on microf. film - roll 105 BK 66 P. 41

Evidence of Subsequent Corner Restoration

Year of search 1983 (March) By Freeman-Olsen
Survey Tech - Forester
End spike in turnaround - also find old
BITS w/ blazes and nails overgrown

Bearing Trees, Reference Objects

Species	Bearing	Tree	Reference Objects
<u>N. PINE</u>	<u>N. PINE</u>		
Diameter <u>8"</u>	<u>12"</u>		
Bearing <u>S29-34W</u>	<u>S69-03E</u>		
Distance <u>33.90'</u>	<u>33.60'</u>		

Bearing Trees, Reference Objects

Species	Bearing	Tree	Reference Objects
<u>TRIPLE Birch</u>	<u>Birch</u>	<u>N. Pine</u>	
Diameter <u>4-6"</u>	<u>9"</u>	<u>6"</u>	
Bearing <u>N7W</u>	<u>N82E</u>	<u>S31E</u>	
Distance <u>40.76'</u>	<u>24.15'</u>	<u>62.65'</u>	

6-17

Subsequent Corner Restoration

Year surveyed Jan 1984 By Freeman-Olsen
Location filed _____
Monument End 2" I.P. Flush
new ties:
Turn 4" Br. oak N19E 8.25' Land Dept tag
5" w. Pine S21W 33.43'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - NARWAY PINE VIEW
BILL SPAIN JR 1959

1953 - Curo - microf. film - roll 155 BK 268 P. 103-104

End stumps of old B.T.'s set 60d spike
new ties:
Birch 4" N77-35E 22.3'
Birch 7" N11-27W 42.87'