


T. 140 R. 30 M. 5TH Coordinates: X _____ Y _____
E146 Corner common to sections 5,6



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument Post

Species	Bearing	Traces
<u>MAPLE</u>	<u>BROAK</u>	
<u>7"</u>	<u>6"</u>	
<u>N65E</u>	<u>N78W</u>	
<u>32 LKS</u>	<u>26 LKS.</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed 1923 By JOHN GREENE
 Location filed COUNTY RESURVEY "E-35"
 Monument 2x48" CAPED I.P.
1965, R.F. SCHNEIDER, BOOK D P. 478 FND I.P. (TIES)

Evidence of Subsequent Corner Restoration
 Year of search 1924 By State Hwy Dept.
R/W map in Recorder's Office - 1/2 mi. to Pine River.
C 1/4 sec. 6 is iron pipe 406.5' W. of rd

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W. PINE</u>	<u>26"</u>	<u>EAST</u>	<u>80.5'</u>
<u>W. OAK</u>	<u>26"</u>	<u>SOUTH</u>	<u>8.1'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

C-5

Subsequent Corner Restoration
 Year surveyed 8/03 By CCSO
 Location filed #2003.059
 Monument Found 2" ODIP w/plumber cap
up 1.9', on side hill. Add the following

<u>10" Maple</u>	<u>N 72° W</u>	<u>17.08' *</u>
<u>5" W. Oak</u>	<u>N 5° W</u>	<u>17.22' *</u>
<u>8" Maple</u>	<u>N 85° E</u>	<u>21.98' *</u>
<u>* distance to double head nail</u>		

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Jim Nielsen - 1983 - Doc # 267919
Found 2" capped pipe. Ties: 6" Burr Oak
N 45 W 29.60'; 5" Burr Oak N 35 E 38.50';
24" White Pine East 81.80'; 5" Maple N 70 W
17.24'.