


Index No. R 14-15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 28 Corner common to sections 22, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1865  
 Original monument lost

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species N. Pine N. Pine \_\_\_\_\_  
 Diameter 12" 10" \_\_\_\_\_  
 Bearing N 3 1/2 W S 5 1/2 W \_\_\_\_\_  
 Distance 28 LKS 23 LKS \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1999 By CCSO  
 Location filed CCSO Job # 98031  
 Monument Fd 3/4" OD IP, up 1.3', 5' south of steps, on top of bank.

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 Species R. Pine R. Pine R. Pine Iron Pipe  
 Diameter 5" 12" 14" 2"  
 Bearing N 20° W N 60° E S 70° E S 5° E  
 Distance 14.53\* 36.38\* 24.92\* 102.68  
 \*distance to dbl. hd. nail

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_