


Index No. L 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 16 Corner common to sections 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>TAM.</u>	<u>TAM.</u>
Diameter <u>8"</u>	<u>10"</u>
Bearing <u>N50E</u>	<u>N54W</u>
Distance <u>12 LKS.</u>	<u>18 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1913 By J.H. FLYNN
Location filed COUNTY BOOK "C" P. 37
Monument FINDLO. GOVT B.T.S. 8" TAM STUMP S50E
12 LKS, 10" TAM STUMP N54W 18 LKS

Evidence of Subsequent Corner Restoration

Year of search 1985 By USFS.
Corner Certificate - Doc # 285569
Set 2 1/2 x 24" i.p. w/ aluminum cap in 4 road
at proportionate (1913) distances

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects	
Species <u>CEDAR</u>	<u>SPRUCE</u>
Diameter <u>6'</u>	<u>7"</u>
Bearing <u>N63W</u>	<u>N82E</u>
Distance <u>35.6'</u>	<u>37.1'</u>

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects		
<u>Metal Post</u>	<u>Metal Post</u>	<u>Metal Post</u>
<u>8' long</u>	<u>8' long</u>	<u>8' long</u>
<u>S83E</u>	<u>S55W</u>	<u>N30W</u>
<u>10.61'</u>	<u>10.89'</u>	<u>15.91'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Ken Whitebarn - USFS - 1985

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____