


T. 141 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 21 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Species	Bearing	Trees	
<u>ASPEN</u>	<u>FIR</u>	<u>FIR</u>	<u>SPRUCE</u>
Diameter <u>26"</u>	<u>10"</u>	<u>6"</u>	<u>12"</u>
Bearing <u>N52W</u>	<u>S60W</u>	<u>S13E</u>	<u>N70E</u>
Distance <u>15 LKS.</u>	<u>29 LKS</u>	<u>26 LKS</u>	<u>14 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

O = Corner

Subsequent Corner Restoration

Year surveyed 1917 By J.H. FLYNN

Location filed COUNTY BOOK C P32

Monument CORNER IN CENTER OF ROAD  
1913 - J.H. FLYNN BOOK C P. 37 FWD ASPEN & NE FIR  
BIT, SET POST

Evidence of Subsequent Corner Restoration

Year of search 1985 By USFS

Corner Certificate - Doc # 285572

End 1913 ties - set 2 1/2 x 2 1/4" 1/4" w/ 3" brass cap  
at intersection N-S & E Rds

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. PINE STUMP</u>	<u>LARGE BULLOCK</u>	
Diameter <u>20"</u>	<u>36"</u>	
Bearing <u>N61E</u>	<u>N49-30W</u>	
Distance <u>42'</u>	<u>37.5'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. Birch</u>	<u>w. birch</u>	<u>Maple</u>
<u>6.7"</u>	<u>5.6"</u>	<u>5.3"</u>
<u>N41E</u>	<u>S45E</u>	<u>S43W</u>
<u>40.03'</u>	<u>33.42'</u>	<u>79.20'</u>
		<u>37.50'</u>

N-13

Subsequent Corner Restoration

Year surveyed 5/04 By CCSO

Location filed #2002.047

Monument USFS Brass cap, down 1.0',  
at intersection of trails. GPS,  
1985 witnesses SE & SW good.  
Maple 8" N40°E, 74.11' \*  
R.Oak 12" N70°W, 26.81' \*  
\*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Ken White Horn - USFS - 1985