


T. 141 R. 26 M. 574 Coordinates: X _____ Y _____
N 1/4 3 Corner common to sections 3 AND 34-141-26



O = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1871
 Original monument POST

Bearing Trees

Species	<u>SPRUCE</u>	<u>SPRUCE</u>	
Diameter	<u>8"</u>	<u>8"</u>	
Bearing	<u>S88E</u>	<u>NRE</u>	
Distance	<u>10 LKS</u>	<u>12 LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1922 By JAMES FLYNN
 Location filed COUNTY BOOK "D" P. 51
 Monument END OLD GOV. B.T. SPRUCE STUMP ALSO
END IRON MONUMENT

Evidence of Subsequent Corner Restoration
 Year of search 1995 2-9 By Lowell Schellack
 Found 6" dia. Concrete cylinder w/ a 3" bronze tablet
stamped to identify the corner - 9" below ground. Left as found
3-01-95 Cert. filed by Lowell Schellack, RLS 1557D.
Doc # 3625506.

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>C.F.P</u>	
Diameter	<u>9"</u>	<u>8" CEDAR</u>	
Bearing	<u>S43W</u>	<u>N30</u>	
Distance	<u>19.7'</u>		

Bearing Trees, Reference Objects

<u>Cedar</u>	<u>Cedar</u>	<u>Birch Stump</u>	<u>Red Pine</u>
<u>14"</u>	<u>15"</u>	<u>6"</u>	<u>10"</u>
<u>N64W</u>	<u>S43W</u>	<u>S34E</u>	<u>S62E</u>
<u>47.00</u>	<u>20.00</u>	<u>23.3</u>	<u>54.27</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - LAKESIDE PARK
JOHN A. GREENE 1913

CERTIFICATE - BILL OKERMAN - 1964
Found iron pipe in place, 9" Cedar S43W
19.7' (now 14" Cedar S44W 20'). Set
6"x24" cylindrical concrete monument
with stamped bronze tablet 4" below
road surface. TIES: 6" Birch S34E
23.3'; 11" Cedar N64W 47.0'; 14"
Cedar S43W 20'.

Aug. 2003 M. Stefan #12261
Cert. of Sur. Shows mon. found