


T. 141 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 10 Corner common to sections R, 3, 10, 11



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1871  
Original monument POST

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	
<u>SPRUCE</u>	<u>SPRUCE</u>	<u>SPRUCE</u>	<u>SPRUCE</u>
<u>7"</u>	<u>8"</u>	<u>10"</u>	<u>3"</u>
<u>N21E</u>	<u>N35W</u>	<u>S60E</u>	<u>S34W</u>
<u>16LKS</u>	<u>13LKS</u>	<u>20LKS</u>	<u>24LKS</u>

Species	Bearing	Trees	Found
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 1995 2-9 By Lowell Schellack  
Found a 2' 10" galvanized iron mon. w/ a 3" brass tablet  
stamped to identify the corner 18" above ground.  
3-21-95 Cert. Filed by Lowell Schellack, RRS 15572,  
Doc. # 365509

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance	Species	Bearing	Distance
<u>Tamarack</u>	<u>8"</u>	<u>38.09</u>	<u>Tamarack</u>	<u>8"</u>	<u>6.5</u>
<u>Tamarack</u>	<u>7" stump</u>	<u>26.90</u>	<u>Tamarack</u>	<u>8"</u>	<u>24.7</u>
<u>Tamarack</u>	<u>11"</u>	<u>20.77</u>	<u>Tamarack</u>	<u>9"</u>	<u>31.95</u>
<u>Tamarack</u>	<u>N22E</u>	<u>38.09</u>	<u>Tam.</u>	<u>S73E</u>	<u>6.5</u>
<u>Tamarack</u>	<u>N35E</u>	<u>26.90</u>	<u>Tam.</u>	<u>S49E</u>	<u>24.7</u>
<u>Tamarack</u>	<u>N12W</u>	<u>20.77</u>	<u>Tam.</u>	<u>S65E</u>	<u>31.95</u>

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_