


T. 141 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species White Pine  
Diameter 24"  
Bearing N 12° W  
Distance 83 links

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 4/1973 By C. Krause, USFS  
Location filed: Field Book 2, page 50  
Monument:  
Chained from Sec. corners N. and S., 100'+/- of Hwy #34,  
found a large Pine Stp. N 13° W, 54.8'. There are other Pine  
stumps in area, none as large. Set 2" Aspen post from stump.  
Placed FSLP on the following.

Bearing Trees, Reference Objects

Species Red Oak  
Diameter 10"  
Bearing N 60° W  
Distance 14'

Evidence of Subsequent Corner Restoration

Year of search 11/1987 By R.L. Kovanen, LS 16459  
Location filed: Certificate of Location  
Monument:  
Found 2" Aspen post and Pine stump from 1973, found another  
30" Pine stump 60' W. Evidence is not conclusive.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 12/1987 By R.L. Kovanen, LS 16459  
Location filed: Certificate of Location T141N R27W  
Monument: Set 2" USFS iron pipe W/brass cap 1/4  
at lost position, 116'+/-, N. of centerline S9 | S10  
Hwy. #200 and witnessed. 1988  
5'x 2.5' Rock, N 85° E, 3.59' to X RLS 16459  
5" Red Pine, S 9° W, 24.57' 20d spike  
Steel Sign Post, North, 4.0'

9/1999, CCHD/SO  
#1999.046  
Found 2" ODIP with brass cap.

8/2018, CCHD/SO  
#2017.018  
Found 2" USFS IP with brass cap, up 1.6', 116'+/-, N. of Hwy.  
#200 and witnesses.  
5'x 2.5' Rock, N 85° E, 3.59'(1987) to X on rock  
10" Red Pine, S 9° W, 24.57'(1987) 20d spike, up 0.7', W. side  
Steel Sign Post, North, 4.0'(1987)


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

Index No. G 17

CASS COUNTY LAND CORNER RECORD

T. 141 R. R7 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 10 Corner common to sections 10, 11



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1874  
Original monument POST

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. PINE  
Diameter 24"  
Bearing N12W  
Distance 83 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 1988 By Robert Kerenen  
Corner Certificate - Doc # 302628  
Set 2x48" 1 lb. w/ brass cap.  
8' steel sign NORTH 4.0'

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
Red Pine 5" 5' x 2 1/2' X on rock  
S 9 W 24.57' N 85 E 3.59'

Subsequent Corner Restoration  
Year surveyed 9/99 By CCSO  
Location filed f. l. e #99046  
Monument Found & Located Brass cap.

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Robert Kerenen - 1988

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_