


T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
E114 B Corner common to sections B, 9



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument POST

Bearing Trees

Species POPLAR

Diameter 8"

Bearing S85E

Distance 11 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLD

Location filed SECRETARY OF STATE

Monument PROPORTIONAL POSITION - NO ORIGINAL EVIDENCE
SET 1 X 36" I.P. W/ BRASS CAP
14
58 | 59
1919

Evidence of Subsequent Corner Restoration

Year of search 1927 By State Hwy Dept
R/W map in Recorders Office - 12 mi. W. to Roney.
iron monument brass cap 407.0' S. of G
1940 - CCC notes - USFS records shows brass cap
monument find - and w. pine B.T. west

Bearing Trees, Reference Objects

Species N. PINE W. PINE

Diameter 16" 74"

Bearing N66-45E N87-30W

Distance 134 LKS 64 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1982 By Gary Stevenson

Location filed Corner Certificate

Monument accept 1940 evidence as perpetuation
of corner.
new B.T. 5'
12" N. Pine N56E 69.30'
7" W. oak S63E 33.28'
15" N. Pine S5W 36.95'
5" W. oak N22W 19.50'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Gary Stevenson - Filed by USFS 1984
Doc # 279826
dated 1982