


T. 141 R. 27 M. 5th Coordinates: X _____ Y _____

NE 16 Corner common to sections 9, 10, 15, 16



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

| Species | Oak | Poplar | Poplar |
|----------|----------|----------|----------|
| Diameter | 8" | 5" | 5" |
| Bearing | N 42° W | S 43° W | S 49° E |
| Distance | 15 links | 11 links | 16 links |

Original Bearing Trees Found

| Species | _____ | _____ | _____ |
|----------|-------|-------|-------|
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 6/1919 By E.G.Harrington, GLO
Location filed: Resurvey Notes, MN Hist. Society T141N R27W
Monument: Found 2" Iron Pipe by Co. Surveyor S 9 | S 10
Set 2"x 36" Iron Pipe with brass cap, flush S 16 | S 15
No Original evidence, position falls in 1919
centerline of E-W road.

Evidence of Subsequent Corner Restoration

Year of search 6/1968 By W.H. Okerman, LS 6807
Location filed: USFS Field Book 2, page 67
Monument: Found GLO iron pipe, cap gone and burned out stump at 1919 bearing and distance.

Bearing Trees, Reference Objects

| Species | Norway Pine | _____ | _____ |
|----------|-------------|-------|-------|
| Diameter | 24" | _____ | _____ |
| Bearing | N 22° E | _____ | _____ |
| Distance | 141 links | _____ | _____ |

Bearing Trees, Reference Objects

| Species | _____ | _____ | _____ |
|----------|-------|-------|-------|
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 6/1968 By L. Elliott, USFS
Location filed: USFS Field Book 2, page 67 T141N R27W
Monument: Set 6" concrete cylinder W/brass cap S 9 | S 10
down 1' in road and witnessed. S 16 | S 15
9" Red Pine, N 28° W, 83.56' scribed 1968
10" White Oak, N 41° E, 60.76' scribed RLS No. 6807
8" White Oak, S 37° E, 62.98' scribed
10" Jack Pine, S 74° W, 64.95' scribed
4" Cedar Post, South, 15.6' 54-2 and 54-4 signs

Evidence of Subsequent Corner Restoration Found

Year of search 10/2005 By CCHD/SO
Location filed: #2001.016
Monument: Found 2.5" ODIP flush, 6'+/-, S. of centerline Co. Rd. #129.
6/2006, CCHD/SO #2005.068
Found 2" ODIP, flush, 7'+/-, S. of centerline Co. Rd. #129.

10/1987, R.L. Kovanen, LS 16459
Certificate of Location, #302620
Found USFS brass cap in concrete, down 0.5', 5'+/-, S. of centerline Co. Rd. #129 and witnesses as follows.
12" Red Pine, N 28° W, 83.56'(1968) 20d spike
12" White Oak, N 41° E, 60.76'(1968) 20d spike
White Oak stub, S 37° E, 62.98'(1968)
13" Jack Pine, S 74° W, 64.95'(1968) 20d spike
4" Cedar Post, South, 15.6'(1968) 54-2 and 54-4 signs
Steel Sign Post, South, 18.9'

8/2018, CCHD/SO #2017.018 T141N R27W
Found 2.5" ODIP, bent and tipped, pieces S 9 | S 10
of concrete monument. Remove and set S 16 | S 15
1" x 30" Aluminum County monument, down 2018
1.0', 6' +-, S. of centerline Co. Rd. #129. RLS 21367
14" W. Oak, N 41° E, 60.76'(1968) duplex nail, up 1.0', E. side
14" Jack Pine, S 74° W, 64.95'(1968) 20d spike, up 0.5', N. side
12" Burr Oak, N 48° W, 48.80' duplex nail, up 1.0', N. side
9" Red Pine, S 58° E, 57.73' duplex nail, up 1.0', S. side
Steel Sign Post, South, 18.9'(1987)


3/2001, Township Officer
Land Corner Record
Concrete Mon. knocked out by grader, ties OK.

11/1/2018, T.L. Freeman, LS 21367
Filed a Certificate of Location of Gov't Corner, as Document #A000645583, on the above information.

Index No. J13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

| | Bearing | Trees |
|----------|---------------|---------------|
| Species | <u>OAK</u> | <u>POPLAR</u> |
| Diameter | <u>8"</u> | <u>5"</u> |
| Bearing | <u>N42W</u> | <u>S43W</u> |
| Distance | <u>15 LKS</u> | <u>11 LKS</u> |

| Original Bearing Trees Found | |
|------------------------------|-------|
| Species | _____ |
| Diameter | _____ |
| Bearing | _____ |
| Distance | _____ |

Subsequent Corner Restoration

Year surveyed 1919 By GLD
Location filed SECRETARY OF STATE
Monument FND 2" I.P. SET 2x36" I.P.W/BRASS CAP
SET 36" IN GROUND - IT FALLS T 141 N R 27 W
IN E-W ROAD. (IN Q) S 9 1 S 10
516 1 515

Evidence of Subsequent Corner Restoration

Year of search 1988 By Robert Kovanen
Corner Certificate - Doc # 302620

Fnd brass capped concrete monument

Bearing Trees, Reference Objects 1919

| | | | |
|----------|----------------|-------|-------|
| Species | <u>N. PINE</u> | _____ | _____ |
| Diameter | <u>24"</u> | _____ | _____ |
| Bearing | <u>N22E</u> | _____ | _____ |
| Distance | <u>141 LKS</u> | _____ | _____ |

Bearing Trees, Reference Objects

| Red Pine | W. Oak | W. Oak Stub | J. Pine |
|---------------|---------------|---------------|---------------|
| <u>12"</u> | <u>12"</u> | _____ | <u>13"</u> |
| <u>N28W</u> | <u>N41E</u> | <u>S37E</u> | <u>S74E</u> |
| <u>83.56'</u> | <u>60.76'</u> | <u>62.98'</u> | <u>64.95'</u> |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKEMAN - 1968

Certificate - Robert Kovanen - 1988

MARCH 2001 - TWP OFFICERS - CONC. MON.
WAS KNOCKED OUT BY GRADER - TIES OK

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____