


T. 141 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>
Diameter <u>5"</u>	<u>6"</u>	<u>6"</u>
Bearing <u>N75E</u>	<u>S33W</u>	<u>S10E</u>
Distance <u>30 LKS</u>	<u>37 LKS</u>	<u>55 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLO  
 Location filed SECRETARY OF STATE  
 Monument END 2" GALV. I.P. SET 1X36" I.P. W/  
BRASS CAP. T141N R27W  
57 | 58  
518 | 517

Evidence of Subsequent Corner Restoration

Year of search 1922 By J. A. FLYNN  
COUNTY BOOK "D" P. 76 FIND GOVT IRON CORNER

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. OAK</u>	<u>10"</u>	<u>N29-30E</u>	<u>399 LKS</u>
<u>R. OAK</u>	<u>20"</u>	<u>N17W</u>	<u>200 LKS</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 9/80 By USFS  
 Location filed USFS Cass Lake BK 1, pg 26  
 Monument Add witness:  
W. Oak 10" N77°E 67.5'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - HOLIDAY ACRES  
JOHN X. STARK 1961

11/85 - USFS Krause found 1969  
Oak witnesses in good condition  
and added the following:  
8" W. Oak S61°E, 34.55'  
10" W. Oak S75°W, 54.6'

CERTIFICATE - BILL OKERMAN - 1969  
Found 1" x 2" iron post with brass cap  
broke off; found rotted stump N29°30'E  
263.3'; found large depression N17W 132'  
Set 6" x 5" concrete monument with  
stamped brass tablet. Ties: 6" W. Oak  
N40E 55.95'; 12" Twin Elm S22E 31.34';  
9" R. Oak S48W 50.67'; 6" Elm NS8W 68.60'  
Cedar post 4x4x72" West 3'.

7/89 - USFS Krause found concrete  
monument broken, replaced with  
2" x 36" iron pipe with Brass cap.  
BT'S all in good shape.