


T. 141 R. R7 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument POST

Species	Bearing	Trees
<u>N. PINE</u>	<u>N10W</u>	<u>10 PINE</u>
<u>N. PINE</u>	<u>N23W</u>	<u>13 PINE</u>
<u>PORLAR</u>	<u>S25E</u>	<u>4</u>
Diameter		
Bearing		
Distance		

Original Evidence Found
 Year of search 1919 By GLO
 Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
<u>PINE STUMP</u>	<u>N10W</u>	<u>65 LKS</u>
<u>PINE STUMP</u>	<u>N23W</u>	<u>75 LKS</u>
Diameter		
Bearing		
Distance		

Subsequent Corner Restoration
 Year surveyed 1913 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK A P564-567
 Monument LOCATED CORNER

Evidence of Subsequent Corner Restoration
 Year of search 1919 By GLO
FIND B.T.S (ABOVE) SET 2x36" IRON POST
36" IN GROUND W/ BRASS CAP. T191N, R27W
518 | 517
519 | 520

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects 1919

<u>W. OAK</u>	_____	_____
<u>8"</u>	_____	_____
<u>S52-30E</u>	_____	_____
<u>299 LKS.</u>	_____	_____

Subsequent Corner Restoration
 Year surveyed 1982 By Gary Stevenson
 Location filed CORNER Certificate
 Monument in 1980 USFS End Brass cap and
remains of 2 orig B.T.S and 1919 B.T. stump
W. oak 8" N3W 55.32'
W. oak 9" N78E 17.40'
W. oak 8" S40E 54.25'
W. oak 8" N33W 53.95'

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Gary Stevenson - filed by USFS 1984
Doc. #279274 dated 1982