


T. 141 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 29 Corner common to sections 28, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Poplar Poplar  
Diameter 4" 5"  
Bearing N 27° E N 36° W  
Distance 38 links 50 links

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 6/1919 By E.G.Harrington, GLO  
Location filed: Minnesota Historical Society  
Monument: Set 1"x 36" Iron Post with brass cap  
Found no evidence of corner, set proportionally  
and witnessed. 1/4  
S29 | S28  
1919

Evidence of Subsequent Corner Restoration

Year of search 8/1920 By L.M. Mackey, Surveyor  
Location filed: Survey Record #443, Book C, page 374  
Monument: Found 1" Iron post set by U.S. Gen. Land Office

Bearing Trees, Reference Objects

Species White Pine Maple  
Diameter 18" 6"  
Bearing S 87°30' E N 55°45' W  
Distance 353 links 29 links

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 6/1923 By J.H. Flynn, Deputy Surveyor  
Location filed: Survey Record #527, Book D, page 116 and Curo  
Monument: I.M.  
Curo Book 190, page 47, N. on graded road 2720' to I.M. 1/4.

Evidence of Subsequent Corner Restoration Found

Year of search 5/2001 By T.L. Freeman, LS 21367  
Location filed: Certificate of Survey  
Monument: Found brass capped monument

1/1936, J.R. Homala, CCC Forester  
USFS, Form 874-9  
Found iron pipe with brass cap, no witness trees.

4/2005, T.L. Freeman, LS 21367  
Certificate of Survey  
Found monument.

6/1968, L. Elliott, USFS  
USFS Field Book 2, page 79  
Set 6" concrete cylinder with brass tablet, stamped RLS 6807  
down 10" in road and witnessed:  
W Pine stump, S 87°30' E, 233.0 (1919)  
8" White Pine, S 88° E, 231.20'  
16" White Pine, S 79° E, 247.87'  
9" White Oak, S 55° W, 73.26'  
9" White Oak, N 89° W, 43.30'

11/2015, CCHD/SO  
#2015.011  
After reconstruction Co. Rd. #129, set 1"x 30" Alum. Co. Mon.,  
down 0.4', 8'+, -, E. of centerline, at intersection of recovered  
witness trees and recovered monuments from 2001 survey.  
10" Burr Oak, N 89° W, 43.30'(1968) 20d nail, up 0.8', N. side  
13" Red Pine, S 88° E, 231.04'(1968) duplex nail, up 0.8', N.  
19" Red Pine, S 79° E, 247.32'(1968) duplex nail, up 0.6', S.  
10" Burr Oak, S 55° W, 73.26'(2001) duplex nail, up 1.0', S.

6/1977, C.R. Krause, USFS  
USFS Field Book 2, page 79  
Set 2" iron pipe with brass tablet  
down 14" in road with rock pile around monument to replace  
broken concrete monument and witnessed:  
8' Steel Post, East, no distance

6/2018, CCHD/SO  
T143N R27W  
Aluminum cap torn off and top 1.0' bent by road grading,  
remove monument.

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 6/2018 By CCHD/SO

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: T143N R27W

Location filed:


Monument: Set 7/8" ODIP, capped RLS 21367  
down 0.8', 8'+/-, E. of centerline and witnesses.  
10" Burr Oak, N 89° W, 43.30'(1968) 20d nail, up 0.8', N. side  
13" Red Pine, S 88° E, 231.04'(1968) duplex nail, up 0.8', N.  
19" Red Pine, S 79° E, 247.32'(1968) duplex nail, up 0.6', S.  
10" Burr Oak, S 55° W, 73.26'(2001) duplex nail, up 1.0', S.  
Steel Sign Post, East, 9.00', up 1.0', S. side

Monument:

Index No. T9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 29 Corner common to sections 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Species	<u>POPLAR</u>	Bearing	<u>POPLAR</u>	Trees	_____
Diameter	<u>4"</u>		<u>5"</u>		_____
Bearing	<u>N77E</u>		<u>N36W</u>		_____
Distance	<u>38 LKS</u>		<u>50 LKS</u>		_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLO  
Location filed SECRETARY OF STATE  
Monument PROPORTIONAL POSITION - NO ORIGINAL  
EVIDENCE - SET 1 X 36" I.P. W/ BRASS CAP. 1/4  
529/528  
1919

Bearing Trees, Reference Objects

Species	<u>W. PINE</u>	Bearing	<u>MAPLE</u>	Reference Objects	_____
Diameter	<u>18"</u>		<u>6"</u>		_____
Bearing	<u>S87-30E</u>		<u>N55-45W</u>		_____
Distance	<u>353 LKS</u>		<u>29 LKS</u>		_____

Evidence of Subsequent Corner Restoration

Year of search 1920 By LINCOLN MACKEY  
COUNTY BOOK C" P. 374 FND GLO 1" IRON  
1923, FLYNN, BOOK "D" P. 116 FND GOVT IRON MONUMENT

Bearing Trees, Reference Objects

Species	_____	Bearing	_____	Reference Objects	_____
Diameter	_____		_____		_____
Bearing	_____		_____		_____
Distance	_____		_____		_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1968  
Found stump for 18" W. Pine S87°30'E  
233.0'. Set 6" x 2' concrete cylinder  
10" under road with stamped brass  
tablet. Ties: 8" W. Pine S88E 231.2';  
16" W. Pine S79E 247.87'; 9" W. Oak  
S55W 73.26'; 9" W. Oak N89W  
43.3'.

MAY 2002 T. FREEMAN  
CERT OF SVY SHOWS MON FOUND

Sept. 2004 T. Freeman #21367  
Cert. of Survey shows monument found

April 2005 T. Freeman #21367  
Cert. of Survey shows monument found

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_