


T. 141 R. R7 M. 574 Coordinates: X _____ Y _____
E114 35 Corner common to sections 35,36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>CEDAR</u>	<u>CEDAR</u>	_____
Diameter	<u>15"</u>	<u>10"</u>	_____
Bearing	<u>N89E</u>	<u>S85W</u>	_____
Distance	<u>10 LKS</u>	<u>8 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1977 By Bert Eveland / DNR
Found 1" iron pipe up 1.4' next to old 3" square wood post up 3'.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Cedar stump</u>	_____	_____	_____
<u>12"</u>	_____	_____	_____
<u>N 80 E</u>	_____	_____	_____
<u>148'</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BERT EVELAND - DNR - 1980
Doc # 258161
1993 12-13: Found iron pipe monument. Removed monument. Placed two 5' sections of alum. rod w/ a 3' stabilizer w/ alum. cap. 5-4-94
Cert. filed by Terry Freeman, RLS 21367, Doc #357319. Ties: 12" Cedar stump N80E 148.00' (1980 DNR BT); 12" Aspen S65E 128.38'; 10" Ash S32E 164.93'