


Index No. 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
5114 31 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ASH</u>	<u>ELM</u>	
<u>5"</u>	<u>6"</u>	
<u>N70W</u>	<u>N7E</u>	
<u>19 LKS.</u>	<u>11 LKS</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By HARRY S. TODD
Location filed COUNTY SURVEY RECORD BOOK A" P568-570
Monument SET 4X4X40" STAKE

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO
FILED AT: SECRETARY OF STATE PROPORTIONAL
LOCATION - END 2' GALV. I.P. SET 2X36" I.P. W/
BRASS CAP, 36" IN GROUND - FALLS IN ROAD SC
14531
1919

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>OAK STUMP</u>	<u>18"</u>	<u>N17-23E</u>	<u>70.80'</u>
<u>PINE STUB</u>	<u>9"</u>	<u>N66-46E</u>	<u>74.25'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPLAR</u>	<u>6"</u>	<u>N20E</u>	<u>245 LKS</u>

Subsequent Corner Restoration

Year surveyed Mar 2003 By CCSO
Location filed _____
Monument Found 1/2 way on E. Co. Rd. 7,
14'± E of E driveway.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

~~*10" Elm S5°W 77.78'
Tele ped post N 60°E 97.00'
Tele ped post S 60°E 89.27'
*Dist. meas to dbl hd rail.
SHOULD BE A-3 140-27~~

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____