


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
N 14 13 Corner common to sections 12, 13



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. PINE</u>	<u>W. PINE</u>	
Diameter <u>26"</u>	<u>20"</u>	
Bearing <u>N 70 E</u>	<u>S 65 W</u>	
Distance <u>10 LKS.</u>	<u>65 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By J. H. FLYNN
Location filed COUNTY BOOK 'B' P 589-591
Monument FIND POST

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO
FILED AT: SECRETARY OF STATE - PROPORTIONAL POSITION
NO ORIG. EVIDENCE. SET 1x36" I.D. W/ BRASS CAP
36" IN GROUND - CORNER 15 IN ROAD & 1/4 S12
513

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>BL. OAK</u>	<u>W. OAK</u>	_____	_____
<u>14"</u>	<u>12"</u>	_____	_____
<u>N 74 E</u>	<u>S 72 W</u>	_____	_____
<u>190 LKS.</u>	<u>220 LKS</u>	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972

Certificate David Landecker 1992
Doc. # 334685
Found 5 1/2 x 5 1/2 x 24" concrete monument
with brass cap down 8". Ties: 12" Red
Oak N 23 W 57.50'; 26" Red Oak N 74 E
125.40'; 6 1/2" Burr Oak S 66 E 40.80';
7" Maple S 27 W 24.90'.