


T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
N1/4 19 Corner common to sections 18, 19



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument POST

Bearing Trees
 Species _____
 Diameter NO B.TS
 Bearing _____
 Distance _____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
 Location filed SECRETARY OF STATE
 Monument PROPORTIONAL POSITION - SET 1x36" I.P. w/ BRASS CAP
1/4 S18
S19
1918

Bearing Trees, Reference Objects
 Species N. PINE N. PINE
 Diameter 6" 8"
 Bearing S56 1/4 E N4 1/2 W
 Distance 151 LKS 306 LKS

Evidence of Subsequent Corner Restoration

Year of search 1917 By E. B. HORST
COUNTY BOOK "C" P. 528 SET 4x4x36" PEP-LAR POST
also on microfilm - roll 115 BK 77 P. 109
at E 1/16 - set 4x4x36" Poplar post - 4" Poplar North
9.0' 3" Poplar West 8.2'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973
1992 Certificate Terry L. Freeman, RLS 21367
Doc # 341348
Found 1" x 3/16" GLO brass cap monument
with 6' steel sign post alongside. TIES:
8" Norway Pine N 4 W 201.96'; 15"
Red Oak N 19 E 139.98'; 14" Norway Pine
S 70 E 78.20'; 16" Norway Pine
S 56 E 99.66'; 8" Tamarack S 42 W
242.32'.

