


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
E114 30 Corner common to sections 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species W. PINE
Diameter 18"
Bearing N80E
Distance 2745

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1916 By E. B. HORST
Location filed COUNTY BOOK 'B' P 384-390
Monument SET 2 1/2 x 48" GALV. I.P. W/ CAP PROPORTIONALLY
1014.87' S OF 1/4 COR SET 2 1/2 x 48" GALV. I.P. W/ CAP ON
S. BOUNDARY RESERVATION
also on microfilm - roll 115 BK 77 P. 86-87

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO
FILED AT: SECRETARY OF STATE
PROPORTIONAL POSITION - SET 1 x 36" I.P. W/ BRASS CAP
1/4
530 / 529
1918

Bearing Trees, Reference Objects

TAM J. PINE
6" 12"
S30E S50W
199 LKS 230 LKS

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc # 311937
Found 1" x 36" iron pipe with brass cap
(GLO) and 2" capped pipe (1916). TIES:
8" Tamarack S75W 55.30'; 8" Spruce
S52W 61.40'; 10" Tamarack S10W
99.90'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____