


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument BUNT FOR CORNER IN POND

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter NO BITS
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument PROPORTIONAL POSITION - NO ORIG. EVIDENCE
SET 2x30" IR. W/ BRASS CAP 1 1/4" R28W
528 | 527
533 | 534

Evidence of Subsequent Corner Restoration

Year of search 1968 By Co Hwy Dept
Colo #5
2" I.P.

Bearing Trees, Reference Objects ¹⁹¹⁸

Species J. PINE PITS
Diameter 7" 18x18x12"
Bearing N22E IN EACH SECTION
Distance 240 LKS 5 1/2'

Bearing Trees, Reference Objects

V-13

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - AUDITORS PLAT OF TONGUILLE
GEORGE CLAYTON 1963
CLAYTON

1989 Certificate - David Landecker
Doc. # 311942
Found 2" GLO Brass cap monument. Ties:
6" Ash N4W 42.75'; 8" Burr Oak N45E
127.39'; 13" White Pine N58E 216.98'.

1999 - R. Mustonen
Cert. of Survey indicates iron
monument fnd.