


Index No. V3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
N14 31 Corner common to sections 30, 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>17"</u>	<u>14"</u>	_____
Bearing	<u>S40E</u>	<u>N19E</u>	_____
Distance	<u>47 LKS</u>	<u>40 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By E. B. HORST
Location filed COUNTY BOOK 'B' P 384-390
Monument SET 2 1/2 x 48" GALV. I.P. W/ BRASS CAP
also on microfilm - roll 115 BK 77 P. 88-89

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO
FILED AT: SECRETARY OF STATE
PROPORTIONAL POSITION SET 1x36" I.P. W/ BRASS CAP
14 530
531
1918

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>4"</u>	<u>6"</u>	_____
Bearing	<u>N14W</u>	<u>S65W</u>	_____
Distance	<u>6.40'</u>	<u>11.20'</u>	_____

Bearing Trees, Reference Objects

Species	<u>POPLAR</u>	<u>W. PINE</u>	_____
Diameter	<u>10"</u>	<u>6"</u>	_____
Bearing	<u>N86 1/2 E</u>	<u>S27W</u>	_____
Distance	<u>18 LKS</u>	<u>33 LKS</u>	_____

Subsequent Corner Restoration

Year surveyed 1968 By Co Hwy Dept
Location filed Co RD # 5
Monument BRASS CAP MONUMENT

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1964
1989 Certificate - David Landecker
Doc. # 311939
Found 1" x 36" GLO iron pipe with brass cap and 2" x 48" 1916 County iron pipe.
Ties: 21" Norway Pine S63 W 39.10'; 2" capped County pipe S30W 44.12'; 23" White Pine S27W 21.04'; 23" Norway Pine S35E 43.05'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____