


Index No. V7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
N 14 32 Corner common to sections 29, 32

O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Species	Bearing	Trees
<u>N. PINE</u>	<u>BIRCH</u>	
Diameter <u>10"</u>	<u>7"</u>	
Bearing <u>N37E</u>	<u>S10W</u>	
Distance <u>56 LKS.</u>	<u>51 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By E.B. Horst
Location filed COUNTY BOOK "B" P 384-390
Monument SET 2 1/2 x 48" GALV. I.P. w/ CAP PROPORTIONALalso on microfilm - roll 115 BK 77 P. 89

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1918 By GLO
Filed at: SECRETARY OF STATE.
PROPORTIONAL POSITION - SET 1x36" I.P. w/ GRASS CAP
529
114 532
1918

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. PINE</u>	<u>W. OAK</u>	
<u>10"</u>	<u>8"</u>	
<u>N57 1/2 W</u>	<u>S30 1/2 W</u>	
<u>180 LKS</u>	<u>154 LKS</u>	

Subsequent Corner Restoration

Year surveyed 1968 By Co Hwy Dept
Location filed Co RD # 5
Monument 2" I.P.

V-7

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311941.
Found 1" x 3/8" GLO brass cap monument
bent over and County capped iron
monument. Set 2" x 48" iron pipe with
brass cap and plastic base with
magnet. Ties: 2" capped County pipe
S26°40' W 40.44'; 18" White Oak S30 W
100.80'; 10" Red Oak N87 E 53.41'; 21"
Norway Pine S35 E 67.54'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____