


Index No. E-F 10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC ON Corner common to sections 9

w 1/16 LINE



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918 SMC
Original monument 1x36" 1/4" W/BASS W
CAP 59 59
W

Bearing Trees

| | | | | |
|----------|----------------|----------------|--|--|
| Species | <u>CEDAR</u> | <u>ELM</u> | | |
| Diameter | <u>8"</u> | <u>10"</u> | | |
| Bearing | <u>N87-15E</u> | <u>S48-15W</u> | | |
| Distance | <u>60 LKS</u> | <u>135 LKS</u> | | |

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 9/2/87 By DNR
Location filed Field notes (also in top file)
Monument Find 1" 1/4" W/BASS
and Cedar N87E 39' (no scribe visible)
52' N. of & old road, 35' S. of top of
ice ridge Location checks with other corners
in the area

Bearing Trees, Reference Objects

| | | | |
|----------|---------------|---------------|---------------|
| Species | <u>Ash</u> | <u>Ash</u> | <u>Ash</u> |
| Diameter | <u>2-5"</u> | <u>6-7"</u> | <u>17"</u> |
| Bearing | <u>N 342°</u> | <u>32°</u> | <u>77°</u> |
| Distance | <u>23.89'</u> | <u>23.45'</u> | <u>40.60'</u> |

DNR DISCS IN TREES

Evidence of Subsequent Corner Restoration

Year of search 9/8/87 By Terry Freeman & DNR
Corner Certificate - Doc # 317852
Visited corner
placed 7' steel sign post w/ survey marker sign
North 1'
used same B.T.'s (converted to bearings)

Bearing Trees, Reference Objects

| | | | |
|----------|-------------------|-------------------|---------------|
| Species | <u>triple Ash</u> | <u>triple Ash</u> | <u>Ash</u> |
| Diameter | <u>2"-5"</u> | <u>6-7"</u> | <u>17"</u> |
| Bearing | <u>N20°W</u> | <u>N37°E</u> | <u>N83°E</u> |
| Distance | <u>23.89'</u> | <u>23.45'</u> | <u>40.60'</u> |

scribed "B.T." (scribed "SMC 59 B.T.")

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1990 Certificate - Walt Curo, RLS 11395
Doc # 317852

Remuneration certificate prepared _____

Filed at _____

By _____

Date _____