


Index No. J-K 4

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC Corner common to sections 18  
ON RE-ESTABLISHED ORIG. MEANDER LINE 27.25 CH. N OF C.E. 11/6

EXISTING SURVEYS



○ = Corner

Original Government Survey

Original Evidence Found

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE METER - 1963  
Found GLO monument in good condition.  
12" Cedar N 21° 30' E 76.185 now 13"; 9"  
Tamarack N 37° 45' W 65.185 now decayed  
stump. New ties: 7" Cedar N 42 W 30.3';  
6" Cedar N 73 1/2 E 6.67'.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_