


T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 20 Corner common to sections 16, 17, 20, 21



O = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1873
Original monument POST

Year of search _____ By _____
Monument found _____

Bearing Trees			
Species	<u>OAK</u>	<u>MAPLE</u>	<u>OAK</u>
Diameter	<u>5"</u>	<u>6"</u>	<u>10"</u>
Bearing	<u>N68E</u>	<u>N66W</u>	<u>S62W</u>
Distance	<u>5 LKS</u>	<u>7 LKS</u>	<u>25 LKS</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK A P. 500-502
Monument FND OLD GOUT BIT 10" OAK S62W 16.5' AND STUMPS; 5" OAK N68E 3.3', 6" MAPLE N66W 4.6', 5" BIRCH S51E 4.0' SET 3x3x36" OAK STAKE

Year of search 1917 By JOHN CURD
COUNTY BOOK C P. 265 FND GOUT BIT: 10" OAK S62W 25 LKS. SET SMALL STAKE, FND ± 10" OLD BIT: 8" DEAD OAK N58E 21.50', KEMPS B.T.S. TAM 12" N39W 68.30', 7" DEAD OAK S34-30W 38.80' also on microfilm - roll 105 BK 56 P. 69

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>DEAD TAM</u>	<u>POPLAR</u>	<u>OAK</u>
Diameter	<u>8"</u>	<u>12"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N50-30E</u>	<u>N38-15W</u>	<u>S18E</u>	<u>S38-30W</u>
Distance	<u>21.5'</u>	<u>71.35'</u>	<u>14.0'</u>	<u>37.75'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

N-9

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 1918 By GLO
Location filed SEL. OF STATE
Monument FND SW, GOUT BIT. SET 2x36" IR. W/ BRASS CAP 36" IN GROUND T14IN P29W TIES: 517 516 R. OAK 10" N67E 107 LKS. 520 521 R. OAK 14" S11-30E 252 LKS. 1918 16" W. PIPE S26-30W 202 LKS, 14" R. OAK N82-15W 193 LKS

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981 DOC. # 261004
Found 2" bent iron pipe. Set 2" x 24" galvanized iron pipe with marked brass cap down 1' below road surface. TIES: 9" R. OAK N84 W 126.20'; 9" R. OAK S35W 68.02'; 9" R. OAK N62 E 120.30'; 8" R. OAK S46 E 50.54'.

Nov. 1914; Twp Rd order shows no survey

5/2001 CCSO crew found USFS brass cap mon. down 1.2', 1' W. of E Diamond Lake Rd. 1980 BT's good.