


Index No. P 17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
e 1/4 22 Corner common to sections 22, 23



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>28"</u>	<u>6"</u>	_____
Bearing	<u>N 40 W</u>	<u>N 10 E</u>	_____
Distance	<u>22 LKS</u>	<u>39 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed SEC. OF STATE  
Monument 1 X 36" 1 1/4 W / BRASS CAP PROPORTIONATE POSITION  
14  
5 22 / 5 23  
1918

Evidence of Subsequent Corner Restoration

Year of search 1980 By Gary Stevenson  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>W. OAK</u>	_____
Diameter	<u>10"</u>	<u>12"</u>	_____
Bearing	<u>N 89-30 E</u>	<u>N 38 W</u>	_____
Distance	<u>36 LKS.</u>	<u>24 LKS</u>	_____

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>	<u>Oak stump</u>
<u>6"</u>	<u>5 1/2 E</u>	<u>9"</u>	<u>7"</u>
<u>5 62 E</u>	<u>11"</u>	<u>5 30 W</u>	<u>N 38 W</u>
<u>10.13'</u>	<u>27.42'</u>	<u>25.97'</u>	<u>159.00'</u>
			<u>GLO</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - GARY STEVENSON - 1981  
Doc. # 261357

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_