


Index No. A 17-18

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
MC # 17 Corner common to sections 2 AND 35 - 142-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>CEDAR</u>	<u>CEDAR</u>
Diameter <u>10"</u>	<u>7"</u>
Bearing <u>N85E</u>	<u>S19E</u>
Distance <u>22LKS</u>	<u>38LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed Sec. of State
Monument End NE B.T. down - Set w.c. MC.
0.40 CH East 1x36" IRW/brass cap T 142N
WC 535 R30W
MC 52
T 142N
1917

Evidence of Subsequent Corner Restoration

Year of search 1981 By Walter Curro
Found 1" x 3/16" iron pipe with brass cap
in good condition.

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects	
Species <u>W. Oak</u>	<u>Balsam</u>
Diameter <u>6"</u>	<u>14"</u>
Bearing <u>North</u>	<u>S41 3/4 E</u>
Distance <u>44LKS</u>	<u>89LKS</u>

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects		
<u>Spruce</u>	<u>Spruce</u>	<u>Spruce</u>
<u>7"</u>	<u>5"</u>	<u>8"</u>
<u>N7° 12' E</u>	<u>N44° 05' E</u>	<u>S71° 51' E</u>
<u>21.66'</u>	<u>34.95'</u>	<u>10.79'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - WALT CURRO - 1981
Doc. # 262629

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____