


Index No. E 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 12 Corner common to sections 112



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Species	Bearing	Trees
<u>W. PINE</u>	<u>W. PINE</u>	
Diameter <u>30"</u>	<u>36"</u>	
Bearing <u>N 1/2 E</u>	<u>S 7 W</u>	
Distance <u>27 LKS</u>	<u>74 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By ROAD SURVEY
Location filed COUNTY BOOK 'D' P. 104-105
Monument IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1917 By GLO
SET 1 X 3/8" I.P. W/ BRASS CAP 1/4 51
512
1917

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>BIRCH</u>	<u>W. OAK</u>	
<u>8"</u>	<u>10"</u>	
<u>S 4 1/2 W</u>	<u>N 23 1/2 E</u>	
<u>33 LKS</u>	<u>123 LKS</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BUTLER SMITH - HWT ENGINEER 1921
Found iron pipe with brass cap. Ties:
10" Poplar S 3° 30' E 43.6'; 12" Poplar
N 44 E 68.0'.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____