


Index No. G 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
C/4 Corner common to sections 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917 GLO
Original monument 1x36" I.P.W. BRASS CAP C/4 S12
1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species R. OAK R. OAK _____
Diameter 6" 5" _____
Bearing N 35E S 31 3/4 E _____
Distance 58 LKS 29 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1962 By PETE MEYER
Location filed _____

Monument Found GLO monument in good condition; 6" Red Oak N 35E 38.28' now oak clump and decayed stump; 5" Red Oak S 31 3/4 E 19.14' now stump hole.

Bearing Trees, Reference Objects

Species Oak Oak _____
Diameter 12" 13" _____
Bearing N 46 1/2 E S 59 W _____
Distance 32.70' 46.0' _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____