


Index No. G 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 12 Corner common to sections 12 and 7-141-29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing	Trees
<u>BIRCH</u>	<u>POPLAR</u>	
Diameter <u>5"</u>	<u>7"</u>	
Bearing <u>S 23 W</u>	<u>S 56 E</u>	
Distance <u>45 LKS</u>	<u>25 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1917 By GLO

Location filed SEC. OF STATE

Monument FIND DECAYED WOOD POST AND SE B.T. STUMP
SET 1 1/2" I.P. W/ BRASS CAP

14
512/57
1917

Evidence of Subsequent Corner Restoration

Year of search 1974 By Milo Stefan

Set 2" x 60" galvanized steel pipe with
brass cap

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPLAR</u>	<u>6"</u>	<u>S 32 1/2 E</u>	<u>112 LKS</u>
<u>R. OAK</u>	<u>12"</u>	<u>S 66 1/2 W</u>	<u>62 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. OAK</u>	<u>6"</u>	<u>N 80 W</u>	<u>95.60'</u>
<u>R. OAK</u>	<u>8"</u>	<u>S 73 W</u>	<u>74.10'</u>
<u>R. OAK</u>	<u>10"</u>	<u>S 38 W</u>	<u>40.00'</u>
<u>R. OAK</u>	<u>7"</u>	<u>S 1 E</u>	<u>29.70'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - MILO STEFAN - 1974 FILED IN 1979
Doc. # 246203

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____