


T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 4 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees
Species	<u>POPULAR</u>	<u>POPULAR</u>
Diameter	<u>3"</u>	<u>12"</u>
Bearing	<u>N55W</u>	<u>S15 1/2 E</u>
Distance	<u>21 LKS</u>	<u>23 LKS</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By M.A. KEMP  
Location filed COUNTY BOOK "C" P. 55  
Monument FIND OLD GOVT B.T.: DOWN 18" POPULAR S15 1/2 E 23 LKS, NEWER B.T.: 15" OAK S83 1/2 E 120 LKS

Evidence of Subsequent Corner Restoration

Year of search 1917 By GLO  
SET 1 X 36" IR. W/ BRASS GR PROPORTIONAL CUT  
1/4 S10  
S15  
1917

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

<u>POPULAR</u>	<u>POPULAR</u>
<u>10"</u>	<u>8"</u>
<u>N14 1/2 E</u>	<u>S58 3/4 E</u>
<u>26 LKS</u>	<u>9 LKS.</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962  
Found GLO monument in good condition;  
10" Poplar N14 1/4 E 17.16' now decayed  
stump; 8" Poplar S58 3/4 E 5.94' now  
decayed stump. Ties: 15" W. Pine S60W  
68.00'