


T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
E1428 Corner common to sections 27,28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>10"</u>	<u>12"</u>	_____
Bearing	<u>S82W</u>	<u>S77E</u>	_____
Distance	<u>22 LKS</u>	<u>30 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>R. OAK</u>	<u>R. OAK</u>
Diameter	<u>9"</u>	<u>12"</u>	<u>10"</u>
Bearing	<u>N62W</u>	<u>N73E</u>	<u>S9W</u>
Distance	<u>7.36'</u>	<u>18.79'</u>	<u>40.21'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. #310872

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____