


T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>R. OAK</u>	<u>W. PINE</u>	
Diameter <u>8"</u>	<u>14"</u>	
Bearing <u>N 11 1/2 E</u>	<u>S 35 1/2 W</u>	
Distance <u>39.45</u>	<u>35.45</u>	

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker  
Location filed \_\_\_\_\_  
Monument Found 2" iron monument with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>MAPLE</u>	<u>Passwood</u>	<u>Red OAK</u>
Diameter <u>6"</u>	<u>8"</u>	<u>9"</u>
Bearing <u>N 16 E</u>	<u>S 88 W</u>	<u>S 28 E</u>
Distance <u>47.02'</u>	<u>41.77'</u>	<u>44.19'</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - Bill Okerman - 1967  
1989 Certificate - David Landecker  
Doc. # 310681