


Index No. J-K-19-20

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5th Coordinates: X _____ Y _____
1/4 Post 21 Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument wood post

Bearing Trees	
Species <u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>22"</u>	<u>28"</u>
Bearing <u>S26E</u>	<u>N13E</u>
Distance <u>4 LKS</u>	<u>34 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed _____
Monument determined position from stumps of orig B.T.'s - no new monument or B.T.'s

Evidence of Subsequent Corner Restoration

Year of search 1985 By Gary Stevenson
Corner Certificate - Doc # 284983

End stumps (rotted) of orig B.T.'s - fit within 2' of computed position from corners. Set 2" sq. mon. w/ aluminum cap

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

J. Pine	J. Pine	J. Pine	Stump	Stump
<u>12"</u>	<u>12"</u>	<u>12"</u>	<u>G10 BT.</u>	<u>G10 BT.</u>
<u>N20E</u>	<u>S70E</u>	<u>S55W</u>	<u>N13E</u>	<u>S26E</u>
<u>36.74'</u>	<u>37.33'</u>	<u>39.01'</u>	<u>22.4'</u>	<u>2.6'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - 1985

Remonumentation certificate prepared _____

By _____

Filed at _____ Date _____